

Ref: 1979/L/35

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 35 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/36

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 36 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/37

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 37 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/38

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 38 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/39

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 39 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/40

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 40 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/41

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 41 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/42

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 42 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/43

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 43 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/44

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 44 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/45

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 45 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/46

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 46 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/47

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 47 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/48

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 48 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/49

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 49 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/50

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 50 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/51

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 51 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/52

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 52 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/53

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 53 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/54

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 54 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/55

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 55 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/56

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 56 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/57

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 57 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/58

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 58 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/59

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 59 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/60

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 60 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/61

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 61 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/62

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 62 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/63

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 63 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/64

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 64 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/65

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 65 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/66

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 66 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/67

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 67 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/68

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 68 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/69

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 69 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/70

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 70 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/71

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 71 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/72

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 72 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/73

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 73 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/74

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 74 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/75

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 75 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/76

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 76 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/77

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 77 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/78

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 78 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/79

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 79 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/80

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 80 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/81

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 81 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/82

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 82 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/83

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 83 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/84

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 84 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/85

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 85 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/86

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 86 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/87

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 87 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/88

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 88 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/89

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 89 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/90

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 90 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/91

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 91 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/92

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 92 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/93

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 93 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/94

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 94 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/95

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 95 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/96

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 96 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/97

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 97 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/98

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 98 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/99

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 99 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/100

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 100 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/101

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 101 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/102

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 102 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/103

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 103 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/104

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 104 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/105

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 105 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/106

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 106 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/107

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 107 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/108

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 108 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/109

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 109 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/110

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 110 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/111

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 111 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/112

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 112 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/113

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 113 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/114

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 114 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/115

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 115 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/116

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 116 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/117

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 117 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/118

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 118 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/119

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 119 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/120

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 120 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/121

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 121 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/122

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 122 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/123

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 123 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/124

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 124 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/125

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 125 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/126

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 126 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/127

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 127 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/128

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 128 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/176

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 176 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/177

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 177 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/178

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 178 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/179

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 179 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/180

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 180 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/181

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 181 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/182

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 182 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/183

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 183 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/184

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 184 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/185

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 185 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/186

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 186 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/194

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 194 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/195

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 195 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/196

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 196 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/197

Project Ref: 1979/P/1839

Construction Sciences Pty Ltd
ABN 74 128 806 735

15/01/2020

1 Fox Road
Acacia Ridge QLD 4110
Australia

BMD Urban

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 197 THE BANKS, 370-398 LOGAN RESERVE ROAD**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences